

## Notification of Discontinuation

**To: All Distributors of STEMCO Wheel End Products**

In addition to the 343-4311 and 343-4307, discontinued on June 17, 2015 and December 16, 2015 respectively (see bulletins #575-0101 and #575-0112), effective immediately, TireMaax® hubcap part numbers 340-4311 and 340-4307 are also discontinued.

DISCONTINUED PART NO.	DESCRIPTION
340-4307	TireMaax® Hubcap - Without Pipe Plug
343-4307	TireMaax® Hubcap - With Pipe Plug
340-4311	TireMaax® Hubcap - Without Pipe Plug
343-4311	TireMaax® Hubcap - With Pipe Plug

Thank you for your continued support of STEMCO.

